



GMP 100.20

INSTALLATION PLAN


FRONT






SIDE



TOP



WHAT YOU NEED

Electrical cable + industrial plug			
	V.230/1/50-60Hz	V.230/3/50-60Hz	V.400/3N/50-60Hz
	17 Amps	10 Amps	6 Amps
Total power required	3,83 kW	3,83 kW	3,83 kW
Differential magnetothermal switch	Idn = 0.03 A	Idn = 0.03 A	Idn = 0.03 A
Ducting	n/a	n/a	n/a
Clearance around the ironer	back: not needed - right: 650 mm - left: not needed		